

Annexure D**BUILDING SAFETY CERTIFICATE**

No.

Dated 25.04.2025

It is certified that the existing building **St. Lawrence Sr. Sec. School** (name of the building or premises) at **Dewalchaur Kham, Rampur Road Haldwani, Nainital** (Address) is having block (s)/Floor(s) as per details below :-


Detail of Block(s) in school	Block (1)	Block (2)
No. of Floors(s) in the Block	1) Ground Floor 2) First Floor 3) Second Floor 4) Third Floor	1) Ground Floor 2) First Floor 3) Second Floor

The building is owned/occupied by **St. Lawrence Sr. Sec. School** (name of the institution) have complied with the Building requirements in accordance with National Building code Rules, and verified by the officers concerned of **C.D PWD Haldwani** (Name of Department/Govt.) on 25.04.25 (date of inspection) in the presence of **Mr. Anil Joshi** (Chairman) **St. Lawrence Sr. Sec. School, Haldwani** (name and address of Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 25.04.25... for a period of2..... Years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Certificate issue on the basis of physical verification only
- 2.
- 3.
- 4.

Issued on 25.04.25 at Haldwani by

Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : 

Name : Lalit Kumar

Designation : Assistant Engineer

Name & Address of Department/Office : C.D. P.W.D.

Haldwani (NRY)